LOCKHEED AIRCRAFT CORP.	CHANGE PROPOSAL X
DATE 2-17-60	AFFECTS: WSPO PROJECT
NAME OF MAJOR COMPONENT FACE PIECE ASSEM.	PART OR LOWEST SUBASSEMBLY PART NO. & MODEL OR TYPE PLEX. HOSE ASSEM. Q-237
TITLE OF PROPOSAL:	SCE HOSE AND ELECTRIC WIRING ASSEM REPLACEMENT
NATURE OF PROPOSAL:	SEE PAGE 2 ICELS AND REPLACES LAC-40 FOR CUSTOMER 1 ONLY.
(LAC-40 NOW APPLIES TO	
	cion if the emergency face heat wires are connected could cause the pilot's head to be pulled downward
until the emergency face It is possible that, when	could cause the pilot's head to be pulled downward meat wires break or pull away from the face piece. the emergency face heat wires come loose from the me attaching studs may be loosened or withdrawn from
until the emergency face It is possible that, when face piece on ejection, t the face piece causing ar ESTIMATED COST AND TIME	could cause the pilot's head to be pulled downward next wires break or pull away from the face piece. the emergency face heat wires come loose from the se attaching study may be loosened or withdrawn from oxygen leak. NVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40)
until the emergency face It is possible that, when face piece on ejection, t the face piece causing ar ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS	could cause the pilot's head to be pulled downward next wires break or pull away from the face piece. the emergency face heat wires come loose from the se attaching study may be loosened or withdrawn from oxygen leak. NVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: None (SP-1918)
until the emergency face It is possible that, when face piece on ejection, t the face piece causing ar ES ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS	could cause the pilot's head to be pulled downward next wires break or pull away from the face piece. the emergency face heat wires come loose from the se attaching study may be loosened or withdrawn from oxygen leak. NVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: Mone (SP-1918) R PARTS: Approx. \$260.00 per Kit
ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS ADDITIONAL FUNDING REQU	could cause the pilot's head to be pulled downward next wires break or pull away from the face piece. the emergency face heat wires come loose from the se attaching studs may be loosened or withdrawn from oxygen leak. INVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: Mone (SP-1918) R PARTS: Approx. \$260.00 per Kit
ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ADDITIONAL FUNDING REQU ADDITIONAL FUNDING REQU	could cause the pilot's head to be pulled downward neat wires break or pull away from the face piece. the emergency face heat wires come loose from the me attaching studs may be loosened or withdrawn from oxygen leak. [NVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40)] RED: Mone (SP-1918) R PARTS: Approx. \$260.00 per Kit RED: SP-1917 (None)
until the emergency face It is possible that, when face piece on ejection, the face piece causing ar ES ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS ADDITIONAL FUNDING REQU TEMS AFFECTED BY PROPOSAL: SAFETY MISSION PERFORM- OPERA PROCE TIVENESS ANCE PROCE	could cause the pilot's head to be pulled downward neat wires break or pull away from the face piece. the emergency face heat wires come loose from the se attaching studs may be loosened or withdrawn from oxygen leak. INVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: Hone (SP-1918) R PARTS: Approx. \$260.00 per Kit RED: SP-1917 (None) INTER- WEIGHT OR SUPPORT NANCE CHANGE- WEIGHT & SUPPORT NANCE ABILITY BALANCE EQUIPMENT NANCE PROCEDURE WEIGHT & SUPPORT NANCE ABILITY BALANCE EQUIPMENT NANCE MANUAL M
ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS ADDITIONAL FUNDING REQU ESTIMATED COST FOR KITS ADDITIONAL FUNDING REQU ITEMS AFFECTED BY PROPOSAL: SAFETY MISSION PERFORM. OPERA TIVENESS PROCE	could cause the pilot's head to be pulled downward next wires break or pull away from the face piece. the emergency face heat wires come loose from the legataching study may be loosened or withdrawn from oxygen leak. INVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: Hone (SP-1918) R PARTS: Approx. \$260.00 per Kit RED: SP-1917 (None) INTER- WEIGHT OR SUPPORT NANCE CHANGE ABILITY BALANCE EQUIPMENT PROCEDURE LIFE MANUAL MANUA
ESTIMATED COST AND TIME ADDITIONAL FUNDING REQU SAFETY MISSION EFFECTIVENESS MAN/HRS. REQ'D. TO ACCOM SOURCE OF PARTS FOR KIT Time Part of the control	could cause the pilot's head to be pulled downward heat wires break or pull away from the face piece. The emergency face heat wires come loose from the me attaching studs may be loosened or withdrawn from oxygen leak. INVOLVED: Approx. \$500.00 (WAS \$250.00 on ECP 40) RED: Mone (SP-1918) R PARTS: Approx. \$260.00 per Kit RED: SP-1917 (None) INTER. WEIGHT OR SUPPORT NANCE CHANGE ABILITY WEIGHT & SUPPORT PROCEDURE LIFE MANUAL MANUA

Approved For Release 2002/11/15 CIA-RDP89B00989#660 300040017-0

NATURE OF PROPOSAL:

- (Study) 1. Design and develop a new face piece hose and wiring assembly which contains all the wires (9) that are required for the face piece. The normal heat wires will have removable connections at the face piece so that emergency face heat may be used independent of the normal circuit which may be shorted. The emergency face heat will be controlled by the existing manual circuit breaker.
 - 2. Procure and evaluate prototype face piece hose and wiring assembly.

(Change Proposal) SEE FIG. I ATTACHED

- Provide a new face piece hose and wiring assembly which includes all required face piece wiring and has a single nine pin connector.
- Provide a breaksway electrical connector on the side of the seat that will separate on ejection without putting a load on the face piece wires.
- 3. Revise aircraft circuitry to accomodate 1 and 2 above.
- 4. Remove all wiring to and within the Q-207 seat pack.
- 5. Provide wiring harness adapters that adapt the Al3A mask to the system described above.

- 6. Provide a wiring adapter that will adapt the "old style" face piece wiring to an airplane that has had the circuitry and electrical disconnect installed.
- 7. Prepare and issue Service Bulletins and fabricate appropriate aircraft provisioning kits.

MOTE:

- 1. This change is compatible with the Q-270 seat pack.
- 2. It is not proposed to supply a wiring adapter that will adapt the new face piece wiring to an unmodified airplane, as it is felt that the airplanes will be modified before the new face piece hose and wiring is available.
- 3. The communications receptacle on the face piece hose will be moved to the lower end in order to use up some of the slack in the communication wires between the receptacle and the helmet.

NEW HOSES FOR FACE PLATES (See Page 5 for Drawing)

FIG. A & D New Hose \$51.95 es.

FIG. B & C New Hose \$21.10 ca.

FIG. E Connector (9 point) 1 Req.)

Plug (Mote for U174/U) 1 Req.) Approx. \$20.00

Wiring

See ammendment attacked Levision "a"

